


Mesh Angle Gauge

Easily Determine the Stretching Angle of Unmarked Stencils

The ISPS Thread Direction/Mesh Angle Gauge is a quick and easy way to reference the mesh angle on any screen, eliminating the guesswork caused by unmarked screens especially in 4-color process printing. In addition, the gauge is very helpful in diagnosing moiré issues caused by screens or films.

Directions

- Use gauge by laying it directly on the screen or film. A moiré pattern appears on the tool at the angle it sees.
- Can be used on coated and un-coated screens, as well as film



OR

